Regarding Road History Certificate

Due to frequent delimitation of ward's the roads in this ward are bifurcated and distributed among different wards. Hence History of these/this road could not be maintained. Now road History is being uploaded to GIS and will be maintained regularly.

Assistant Engineer	Assistant Executive Engineer	Executive Engineer
Ward No	Yeshwanthpura Sub Division	Rajarajeshwarinagara Division

Regarding Quality Control Certificate

On verification of Quality control test reports available in the file and also from inspection report of the Technical Team deployed for this purpose generally the work executed is satisfactory compliance of Quality Control test reports as per MORT & H this stage is not feasible since the work was executed 2 (two) years back.

Assistant Engineer	Assistant Executive Engineer	Executive Engineer
Ward No	Yeshwanthpura Sub Division	Rajarajeshwarinagara Division